

Reviewing Agency:

Review Date:

Reviewed By:

Project Name: 22 SITE 2 (Western Group, LLC)

Project Location: 245 Route 32 (Map 70 Lot 10)

Comments:

1. Prior to demolition of the garage, an asbestos inspection must be completed. If asbestos is found an abatement must be conducted.

Electronic Signature: *Michael J. Kirby, R.S.*

