

Reviewing Agency: Uncas Health District
Review Date: March 16, 2022

Reviewed By: Michael J. Kirby, R.S., Chief Environmental Sanitarian.

Project Name: 22 SITE 2 (Western Group, LLC)
Project Location: 245 Route 32 (Map 70 Lot 10)

Comments:

1. In addition to the garage, an asbestos inspection of the house must also be completed. If asbestos is found an abatement must be conducted.

Electronic Signature: *Michael J. Kirby, R.S.*